

# Oil Field Environmental Incident Summary

**Incident:** 20160202102215      **Date/Time of Notice:** 02/02/2016 10:22

**Responsible Party:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** WADE FEDERAL 5300 30-29 CTB 2

**Field Name:** BAKER

**Well File #:**

**Date Incident:** 2/2/2016      **Time Incident:** 00:01      **Facility ID Number:** 228303-01

**County:** MCKENZIE      **Twp:** 153      **Rng:** 100      **Sec:** 30      **Qtr:** NE SW

**Location Description:** Wade CTB, oil sprayed south of flare crossing fence on to pasture land

**Submitted By:** Todd Hanson

**Received By:**

**Contact Person:** Dustin Anderson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	35	Gallons				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

no risk

**Areal Extent:**

The oil sprayed an area of approximately 20' by 50'

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

the spill has been reported to our environmental group and a plan of action is being discussed.

**Wastes Disposal Location:** production facility

**Agencies Involved:**

**Updates**

---

**Date:** 2/2/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release did not remain on location. Further followup is necessary.

---

**Date:** 2/10/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 1450. Walked outside perimeter of well pad near the two flares. Release was easily located by the presence of oil-stained vegetation. No cleanup efforts have been made at this point. Photos of the release can be found in the report folder.

---

**Date:** 5/20/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 14:15, 5/20/2016.

No sign of impacts at the time of inspection. There appears to be an area that was scraped up.

No on-site inspection necessary.

---

**Date:** 5/23/2016    **Status:** Awaiting Documentation

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Contact company for follow-up report with any associated sample and test results.

Awaiting documentation.

---

**Date:** 5/25/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on pad at 1650. There is a large portion of the release area that looks to be scraped. Vegetation has flourished along the fence near the flares, where most of the hydrocarbon was released. Further follow-up required on the bare, scraped ground. Photos are in the folder.

---

**Date:** 11/3/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 4:14, 11/3/2016.

Impacted area appears to have sporadic vegetation growing throughout. Follow up with company to ensure proper seeding.

Follow-up is necessary.